


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	05/23/2012	1845		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #9	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	05/23/2012 0900
	Position:	Operations Section Chief	To:	05/23/2012 1800
7. Personnel Roster Assigned				
Name	ICS Position	DUTY CELL		
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Hugh Murrell	SOTF#9			
8. Activity Log				
Activity Area	MP 18.80 to 18.95.	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team 6 Activity:</u></p> <p>SOTF#9 Hugh Murrell (START), Enbridge Team Lead Blake Schwartz, and Leica operator Russell Platte performed poling at 9 locations within focus area 18.80 – 18.95. A total of 3 locations had an overall submerged oil category of none, and 6 locations had a category of light.</p> <p>Due to lack of availability of a functioning Leica, our team did not leave the ICP until approximately 1100 hours. We met with Tetra Tech Team H to shadow them and have them shoot some locations with their Leica for us to perform poling. We ended up delineating an area that Team H had found some Heavy areas of sheen. This was in area 18.80. We did not find the same heavy area, but we delineated it anyway.</p> <p>We then poled the 19.45 N area.</p> <p>We had to take a safety stand down from 1535 to 1640.</p>			

Health and Safety Issues	None
Comments	